

PACIFIC

Jeppesen NavData CHANGE NOTICES highlight only **significant** changes affecting Jeppesen navigation data that may be currently stored in your aircraft navigation system database.

IMPORTANT: CHECK FOR NOTAMS AND OTHER PERTINENT INFORMATION PRIOR TO FLIGHT.

FOR NavData BASE
12 Jun 25 THRU 09 Jul 25 CYCLE 2506

GENERAL

VIETNAM

Transition altitude for all terminal procedures should read 9000' except locations listed below:

VVBM: transition altitude 10,000'

VVDL: transition altitude 10,000'

VVTS: transition altitude 18,000'

NAVAID

BAGUIO NDB 'BG' 272KHz UNSERVICEABLE. REFER SUP 028-24.

BASCO NDB 'BS' 276KHz UNSERVICEABLE. REFER SUP 029-24.

BASCO DME 'BS' CH107X UNSERVICEABLE. REFER SUP 030-24.

BUON MA THUOT From 0000Z 12 JUN 2025 to 0000Z 10 JUL 2025 Buon Ma Thuot DVOR/DME (BMT) 112.100MHz CH-58X will be unserviceable for repair.

DUMAGUETE VOR 'DGT' 114.1MHz UNSERVICEABLE. REFER SUP 026-24 AIRAC.

HOUEI SAY Houei Say (HOU) NDB, freq 250.00KHz completely withdrawn.

IZUMO From 1500Z 22 JAN 2025 to 1500Z 06 AUG 2025 Izumo VOR/DME (XZE) will be unserviceable due to construction. Temporary operation of Hakuto VOR/DME(THE) 110.45 MHz CH-41Y, N 35 25.0 E 132 53.4.

JOMALIG DVOR/DME 'JOM' 116.7MHz/CH114X, DVOR PART UNSERVICEABLE. REFER AIR SUP 031-24.

LUDAO Based on SUP 06-24 LUDAO VOR (GID) unserviceable.

PATTANI Pattani (PT) NDB 201 KHz remains unserviceable due to withdrawn until further notice.

SONGTAN From 1600Z 11 JUN 2025 to 1600Z 08 JUL 2026 the SONGTAN VORTAC (SOT) will be unserviceable due to replacement.

SURAT THANI From 0001Z 11 JUL 24 to 0001Z 09 MAY 26 STN DVOR/DME will be temporarily suspended due to relocation.

SURAT THANI Surat Thani VOR/DME [STN] is temporarily suspended. Wpt SAPUD (090746. 24N 0990805.09E) is established at the same coordinates as Surat Thani VOR/DME [STN], until 9 May 2026.

SUVARNABHUMI From 0001Z 07 SEP 2023 to 0949Z 02 OCT 2025 SVB DVOR/DME will be temporary suspended due to relocation.

SUVARNABHUMI From 0001Z 28 NOV 2024 to 0949Z 02 OCT 2026 Suvarnabhumi DVOR/DME SVB 111.4 MHZ, CH51X will be temporary suspended due to relocation.

WANGSAN From 1600Z 30 OCT 2024 to 1600Z 30 JUN 2025 the WNG VOR/DME at Incheon Intl Airport will be unserviceable due to replacement.

ENROUTE

VIETNAM

A1 BUNTA to KANGU MOCA 8600' (N16 E108).

The following airways and segments within Vietnam will not be approved for overflight:

G221 direction from Phu Cat VOR, PCA to BUNTA.

W1-A1 direction from Tan Son Nhat VOR, TSN-W1-Da Nang VOR, DAN-A1-BUNTA

Q2-A1 direction from TSN - Q2 - PATNO-A1-BUNTA.

TERMINAL

CAMBODIA

VDSS, Dara Sakor Intl

Dara Sakor, Acpb procs: ILS Rwy 21, RNP Rwy 03, RNP Rwy 21, VOR/DME Rwy 03, VOR/DME Rwy 21 should not be used UFN.

Operation of VDSS airport postponed. Do not use SID procedures.

Operation of VDSS airport postponed. Do not use STAR procedures.

VDPP, Phnom Penh Intl

Phnom Penh, Pilots operating at VDPP are advised to be aware of the new airport project located 12 NM South Southeast of VDPP. The construction of the new airport is more than 90% completed. This indicates that the construction has already reached a dimension which makes it possible to see the new airport under construction from the air including the movement area and the passenger terminal. The new airport has one runway with designation 05/23 and dimensions 13123' X 197' (4000m X 60m).

Pilots are advised to exercise heightened situational awareness when operating in the vicinity of VDPP and note that the new airport under construction is not available for operational use until further notice.

PACIFIC**JAPAN****RJCJ, Chitose**

Sapporo, CHITOSE 4 [CHE4] Rwy 36R/36L transition is not available in the database

RJCR, Rebun

Rebun, Until 1500 UTC 31 MAR 2026, operations of Rebun airport are suspended.

RJEC, Asahikawa

Asahikawa, Apch proc COPTER ILS X or LOC X Rwy 34 should not be used due to u/s of ILS-LOC 34 (IAW) until 02 Oct 25.

From 1500Z 11 JUN 2025 to 1500Z 01 OCT 2025 Asahikawa ILS-LOC34 (IAW) will be temporarily located at N 43 41.0 E 142 26.4.

RJFN, Nyutabaru Aero

Nyutabaru, Apch procs: ILS Z or LOC Z Rwy 28, ILS Y or LOC Y Rwy 28, ILS X or LOC X Rwy 28 should not be used until 27 NOV 2025 due to temporary closure of Rwy 10/28.

Until further notice Nyutabaru ILS-GP28 will be unserviceable due to maintenance.

RJNH, Hamamatsu

Hamamatsu, LDI (Rwy 09/27) at Hamamatsu AD is unserviceable due to trouble.

RVR data Rwy 09 Thr side at Hamamatsu AD is not provided due to trouble.

RJNT, Toyama

Toyama, Apch proc VOR A: Alt at MAP should read 'at' 670'. Eff 30 Jun 25.

RJOE, Akeno Aero

Akeno, Due to radar equipment malfunction following frequencies are unserviceable at Akeno AD: Akeno Approach 139.450MHz, 141.950MHz and Akeno GCA 141.700MHz.

RJOW, Iwami

Iwami, From 1500Z 19 MAR 2025 to 1500Z 01 OCT 2025 Iwami ILS-LOC 11 (IWA) will be temporarily located at N 34 40.4 E 131 48.2.

RJOZ, Ozuki Aero

Shimonoseki, Ozuki PAPI will be unserviceable due to flight check result.

RJTA, Atsugi Aero

Atsugi, SID Procs YOKOTA 2 [YOK2], ZUSHI 1 [ZUSHI1] temporary climb gradient for Rwy19 as follow: 4.5% climb gradient required up to 600FT. Obst Alt 498FT locate at 2.2NM 186° FM end of Rwy19, until 1500UTC 30 Sep 2025.

RJTL, Shimofusa Aero

Matsudo, Apch procs: ILS Z or LOC Z Rwy 19, ILS Y or LOC Y Rwy 19 should not be used due to u/s of ILS-LOC 19 (ISH) UFN.

From 0000Z 12 JUN 2025 until further notice Shimofusa ILS-GP 19 will be unserviceable due to construction.

From 0000Z 12 JUN 2025 until further notice Shimofusa ILS-LOC 19(ISH) will be unserviceable due to construction.

From 0000Z 12 JUN 2025 until further notice Shimofusa MM 19 will be unserviceable due to construction.

KOREA**RKJB, Muan Intl**

Muan, Apch procs ILS Z or LOC Z Rwy 01 and ILS Y or LOC Y Rwy 01 should not be used until 02 Oct 2025 due to unserviceability of IMUN ILS/DME.

Apch procs: ILS Z or LOC Z Rwy 19, ILS Y or LOC Y Rwy 19 should not be used until 30 AUG 25 due to ILS/DME (IMAN) unserviceability.

From 0000Z 16 MAR 2024 to 0000Z 31 DEC 2025 the primary surveillance radar at Muan Intl Airport will be unserviceable due to radar replacement work.

From 1600Z 16 APR 2025 to 1500Z 30 AUG 2025 the ALS for Rwy 01 at RKJB will be unserviceable due to work in progress.

From 1600Z 21 FEB 2024 to 1500Z 02 OCT 2025 the ALS for Rwy 19 at RKJB will be unserviceable due to replacement work in progress.

From 1600Z 21 FEB 2024 to 1500Z 02 OCT 2025 the ILS/DME for Rwy 01 at RKJB will be unserviceable due to Rwy 01 LOC replacement.

From 1600Z 30 OCT 2024 to 1500Z 30 AUG 2025 the ILS/DME IMAN for Rwy 19 at RKJB will be unserviceable due to Rwy 19 ILS/DME replacement work in progress.

RKJJ, Gwangju

Gwangju, Apch procs: ILS/DME Rwy 04R, LOC/DME Rwy 04R should not be used until 25 DEC 2025 due to ILS/DME replacement.

From 1600Z 02 OCT 2024 to 1600Z 24 DEC 2025 the ILS/DME for Rwy 04R at Gwangju Airport will be unserviceable due to replacement.

RKJY, Yeosu

Yeosu, Due to Yeosu radar unserviceability, STAR procedures of RKJY are available by using Sacheon radar until 1459 UTC 30 JUN 2025.

SID procs ANUBA 1M RNAV [ANUB1M], ANUBA 1R RNAV [ANUB1R], POVOR 1M RNAV [POVO1M], POVOR 1R RNAV [POVO1R], POVOR 6R RNAV [POVO6R], TEDAN 1M RNAV [TEDA1M], TEDAN 1R RNAV [TEDA1R] are not available due to Yeosu Radar unserviceability until 1459 UTC 30 JUN 2025.

RKSI, Incheon Intl

Seoul, From 1600Z 09 JUL 2025 to 0900Z 01 AUG 2025 Rwy 15L/33R between Twy K and L will be closed due to pavement construction. Eff 09 Jul 25.

From 1600Z 09 JUL 2025 to 0900Z 25 SEP 2025 Rwy 15L/33R between Twy J and K will be closed due to pavement construction. Eff 09 Jul 25.

From 1600Z 20 MAR 2025 to 2200Z 30 JUN 2025 Rwy 15L/33R between Twy J and L will be closed due to pavement construction.

From 2200Z 20 MAY 2025 to 1600Z 09 JUL 2025 aircraft stands number 616, 636 will be closed due to pavement construction.

From 2200Z 30 APR 2025 to 0900Z 30 JUN 2025 aircraft stands number 632, 633, 634 will be closed due to pavement construction. Aircraft stand number 631 will be up to Code C aircraft.

From 2200Z 30 JUN 2025 to 1600Z 09 JUL 2025 Rwy 15L/33R between Twy K and L and between Twy J and K will be closed due to pavement construction. Eff 30 Jun 25.

PACIFIC

ILS or LOC Rwy 16L, ILS or LOC Rwy 16R, ILS or LOC Rwy 34L, ILS or LOC Rwy 34R apch procs - alternative missed approach procedure due to unserviceability of WNG VOR/DME:

Rwy 16L/R: Follow published procedure. If unable, climb to 3 000', after passing 500' fly HDG 190 then radar vector.

Rwy 34L/R: Follow published procedure. If unable, climb to 3 000', after passing 500' fly HDG 280 then radar vector.

ACFT shall advise ATC (Seoul APP/Incheon TWR) for alternatives. RADAR service will be provided by Seoul APP.

SID procs SONGTAN 1S [SOT1S], SONGTAN 1A [SOT1A] not available due to SOT VOTRAC temporary unserviceability until 1600 UTC 8 JUL 2026.

STAR procs GUKDO 1A [GUKD1A], KARBU 1A [KARB1A] not available due to SOT VOTRAC temporary unserviceability until 1600 UTC 8 JUL 2026.

RKSS, Gimpo Intl

Seoul, From 1600Z 14 MAY 2025 to 1600Z 26 NOV 2025 aircraft stands number 35 to 36, 209, 201, 201R, 202 to 203 will be closed due to pavement construction.

SID procs SONGTAN 1E [SOT1E], SONGTAN 1W [SOT1W] not available due to SOT VOTRAC temporary unserviceability until 1600 UTC 8 JUL 2026.

MACAO

VMMC, Macao Intl

Macao, CONV SID NLG 1F [NLG1F] and RNAV SID NLG 1H [NLG1H] not available in database due to descending altitude at NLG VOR until further notice.

PHILIPPINES

RPMZ, Zamboanga Intl

Zamboanga, SIDs BURCO 2A [BURC2A], BURCO 2B [BURC2B], BURCO 2C [BURC2C], BURCO 2D [BURC2D], COGEL 2A [COGE2A], COGEL 2B [COGE2B], GOSTO 2A [GOST2A], GOSTO 2B [GOST2B], MASUN 2A [MASU2A], MASUN 2B [MASU2B], MASUN 2C [MASU2C], MASUN 2D [MASU2D], PARAL 2A [PARA2A], PARAL 2B [PARA2B], PARAL 2C [PARA2C], PARAL 2D [PARA2D], PILAS 2A [PILA2A], PILAS 2B [PILA2B], TABUL 2A [TABU2A], TABUL 2B [TABU2B], TANAL 2A [TANA2A], TANAL 2B [TANA2B], TINDO 2A [TIND2A], TINDO 2B [TIND2B], TINDO 2C [TIND2C], TINDO 2D [TIND2D] suspended, Est 14 Aug 25.

STARs BURCO 1 [BURCO1], COGEL 1 [COGEL1], GOSTO 1 [GOSTO1], MASUN 1 [MASUN1], PARAL 1 [PARAL1], PILAS 1 [PILAS1], TABUL 1 [TABUL1], TANAL 1 [TANAL1], TINDO 1 [TINDO1] suspended, Est 14 Aug 25.

RPVM, Mactan-Cebu Intl

Lapu-Lapu, SIDs ALDIN 2A [ALDI2A], ALDIN 2B [ALDI2B], BAMPA 2A [BAMP2A], BAMPA 2B [BAMP2B], BATAY 2A [BATA2A], BATAY 2B [BATA2B], BOHOL 2A [BOHO2A], BOHOL 2B [BOHO2B], COBOL 2A [COBO2A], COBOL 2B [COBO2B], DIMLO 2A [DIML2A], DIMLO 2B [DIML2B], KANON 2A [KANO2A], KANON 2B [KANO2B], MOLOC 2A [MOLO2A], MOLOC 2B [MOLO2B], PARAO 2A [PARA2A], PARAO 2B [PARA2B], PONSO 2A [PONS2A], PONSO 2B [PONS2B], TADAG 2A [TADA2A], TADAG 2B [TADA2B] suspended, Est 25 Jun 25.

STARs ALDIN 1 [ALDIN1], BAMPA 1 [BAMPA1], BATAY 1 [BATAY1], BOHOL 1 [BOHOL1], COBOL 1 [COBOL1], DIMLO 1 [DIMLO1], KANON 1A [KANO1A], MOLOC 1 [MOLOC1], PARAO 1 [PARAO1], PONSO 1 [PONSO1], TADAG 1A [TADA1A] suspended, Est 25 Jun 25.

TAIWAN

RCBS, Kinmen

Kinmen, RNP Rwy 06 Apch Proc suspended, until 30 Jun 25.

RCFN, Fongnian

Taitung, Apch Proc LDA Rwy 04: Initial Approach transitions GID and ORRIS not available. ATC to provide radar vectoring service to intercept GID 31DME ARC or issue direct OPTIM (IF).

SIDs HYPER 2A [HYPE2A], HYPER 1B [HYPE1B], HYPER 1C [HYPE1C] suspended due to VOR GID unserviceability until 31 Dec 26.

RCNN, Tainan Aero

Tainan, Apch Proc RNP Rwy 36R is not available, UFN.

RCSS, Songshan

Taipei, Apch Proc VOR Rwy 10 should not be used, UFN.

App Proc RNP Rwy 10 is not available (during the operational hours daily 2300-0900 UTC and weather condition reported at Taipei/Songshan airport is VMC)
effect from 30 JUN 2025, 2300 UTC until 26 MAR 2026, 0900 UTC. Eff 30 Jun 25.

RCYU, Hualien

Hualien, Apch Proc ILS Rwy 03 and LOC Rwy 03: FOPIN and JICHI holding patterns are not available. IAF JICHI not available. ATC to provide radar vectoring on request until 31 DEC 2026.

Apch Proc VOR-B: WAGON holding pattern not available, ATC to provide radar vectoring on request until 31 DEC 2026.

PACIFIC**THAILAND****VTBS, Suvarnabhumi Intl**

Bangkok, Runway 01/19 will be closed for preventive maintenance as detailed below:

17, 21, 24, 28 APR 2025, 01, 05, 08, 12, 15, 19, 22, 26, 29 MAY 2025, 02, 05, 09, 12, 16, 19, 23, 26 JUN 2025 in hours 1900-2330Z.

Runway 02R/20L will be closed for preventive maintenance as detailed below:

18, 25 APR 2025, 02, 09, 16, 23, 30 MAY 2025, 06, 13, 20, 27 JUN 2025 in hours 1900-2315Z.

22, 29 APR 2025, 06, 13, 20, 27 MAY 2025, 03, 10, 17, 24 JUN 2025 in hours 1900-2330Z.

Runway 02L/20R will be closed for preventive maintenance as detailed below:

18, 25 APR 2025, 02, 09, 16, 23, 30 MAY 2025, 06, 13, 20, 27 JUN 2025 in hours 1900-1930Z, 2200-2315Z.

22, 29 APR 2025, 06, 13, 20, 27 MAY 2025, 03, 10, 17, 24 JUN 2025 in hours 1900-1930Z, 2200-2330Z.

19, 23, 26, 30 APR 2025, 03, 07, 10, 14, 17, 21, 24, 28, 31 MAY 2025, 04, 07, 11, 14, 18, 21, 25, 28 JUN 2025 in hours 1900-2330Z.

VTBW, Watthana Nakhon

Watthana Nakhon, From 0001Z 17 APR 2025 to 1100Z 31 AUG 2025 Runway edge light is unavailable.

From 0001Z 17 APR 2025 to 1100Z 31 AUG 2025 Runway Threshold light is unavailable.

VTCC, Chiang Mai Intl

Chiang Mai, Aircraft stand number 1 closed for improvements to enhance aircraft parking compatibility.

From 0001Z 13 JUN 2024 aviation gasoline (AVGAS 100LL) is temporarily not available.

Runway 18/36 will be closed for preventive maintenance from 12 to 30 JUN 2025 and from 01 to 11 JUL 2025 daily between 1800-2300Z.

Aircraft operators are advised to avoid using Chiang Mai International Airport as an alternate aerodrome during the runway closure period.

VTPO, Sukhothai

Sukhothai, Apch proc ILS or LOC Rwy 36 should not be used until 30 Nov 2026 due to suspension of ISKT ILS/DME.

From 0001Z 03 OCT 2024 to 1659Z 30 NOV 2026 ILS/DME Rwy 36 (ISKT) Sukhothai is unusable due to scheduled maintenance on the airport's high voltage electrical system.

VTSE, Pathiu

Chumpon, From 0000Z 15 MAY 2025 to 1300Z 24 OCT 2025 operational hours of Aerodrome Operator, Air Traffic Services Reporting Office (ARO) and Air Traffic Services (ATS) will be performed on Mon, Wed, Fri and Sun between 0000-1300Z.

VTSK, Pattani

Pattani, Apch procs NDB Rwy 08 and NDB Rwy 26 should not be used due to temporary withdrawal of PT NDB.

VTSP, Phuket Intl

Phuket, From 0000Z 28 NOV 2024 RVR of Runway 09 and Runway 27 at Phuket Airport is unavailable.

Runway 09/27 will be closed for maintenance works daily in hours 1830-0030Z in the following dates: 30, 31 MAR, 01-30 APR, 01-31 MAY, 01-30 JUN, 01-31 JUL, 01-31 AUG, 01-30 SEP, 01-25 OCT 2025.

VTSS, Hat Yai Intl

Songkhla, The Approach Lights (SALS) of runway 08 and runway 26 at Hat Yai International Airport (VTSS) will be unserviceable.

The Sequenced flashing lights of runway 08 and runway 26 at Hat Yai International Airport (VTSS) will be unserviceable.

VTST, Trang

Trang, From 0001Z 12 JUN 2025 until further notice TRANG GP (335.0 MHz, 073030.79N 0993634.69E) will be temporarily suspended due to the group of highest trees at 0.8NM-0.5NM to runway threshold.

From 10 APR 2022 at 0100Z to 30 OCT 2025 at 2200Z the approach lighting at runway 08 will be removed and therefore become unserviceable.

VTUI, Sakon Nakhon

Sakon Nakhon, From 0100Z 12 JUN 2025 to 2200Z 30 DEC 2025 the revision works will be performed on airfield lighting systems daily between 0100-1000Z and 1300-2200Z except when flights are operated.

VTUK, Khon Kaen

Khon Kaen, From 0100Z 12 JUN 2025 to 2200Z 30 DEC 2025 the construction works at Khon Kaen airport include overlay of runway 03/21 and revision of airfield lighting systems will be performed daily between 0100-1000Z and 1400-2200Z except when scheduled flights are operated.

VTUO, Buriram

Buriram, Thailand, From 0001Z 03 OCT 2024 to 0001Z 04 DEC 2029 ILS/DME Rwy 04 Buri Ram (IBRM), frequencies LOC 109.30MHz, GP 332.00MHz, DME Ch 30X will be temporarily suspended due to the construction of the airport.

From 1301Z 12 JUN 2025 to 0000Z 31 OCT 2025 Runway 04/22 will be closed due to revision of runway lighting systems daily between 1301-0000Z, except when flights are operated.

VTUU, Ubon Ratchathani

Ubon Ratchathani, From 0001Z 03 OCT 2024 to 0001Z 25 DEC 2025 Ubon Ratchathani Rwy 23 IGP (IUBL) 334.40MHz will be temporarily suspended due to groups of high trees as obstacles effected the Glide Path radiation.

VTUV, Thawatchaburi

Roiet, From 1320Z 15 MAY 2025 to 2300Z 31 AUG 2025 the maintenance works for runway 18/36 will be performed daily between 1320-2300Z except when flights are operated.

From 1320Z 20 MAR 2025 to 2200Z 29 JUN 2025 installation works include installation of runway 18/36 turn pad lights will be performed daily between 1320-2200Z except when flights are operated.

PACIFIC

VIETNAM

VVBM, Buonmathuot

Buonmathuot, Apch procs: ILS V Rwy 09, ILS W Rwy 09, ILS X Rwy 09, ILS Y Rwy 09, ILS Z Rwy 09 should not be used until 10 Jul 25 due to DVOR/DME (BMT) repair.

Apch procs: VOR V Rwy 09, VOR W Rwy 09, VOR X Rwy 09, VOR Y Rwy 09, VOR Z Rwy 09, VOR V Rwy 27, VOR W Rwy 27, VOR X Rwy 27, VOR Y Rwy 27, VOR Z Rwy 27 should not be used until 10 Jul 25 due to DVOR/DME (BMT) repair.

SID procs MEVON 1A [MEVO1A], ENGIM 1A [ENGI1A], NOBID 1A [NOBI1A], ONEBI 2A [ONEB2A], DOVIN 1A [DOVI1A], ENRIN 1A [ENRI1A], PATMA 1A [PATM1A], MEVON 1B [MEVO1B], ENGIM 1B [ENGI1B], NOBID 1B [NOBI1B], ONEBI 2B [ONEB2B], DOVIN 1B [DOVI1B], ENRIN 1B [ENRI1B], PATMA 1B [PATM1B] suspended due to BMT DVOR/DME shutdown period until 0000 UTC 10 JUL 2025.

STAR procs MEVON 1C [MEVO1C], ENGIM 1C [ENGI1C], NOBID 1C [NOBI1C], ONEBI 2C [ONEB2C], DOVIN 1C [DOVI1C], ENRIN 1C [ENRI1C], TANGO 1C [TANG1C], MEVON 1D [MEVO1D], ENGIM 1D [ENGI1D], NOBID 1D [NOBI1D], ONEBI 2D [ONEB2D], DOVIN 1D [DOVI1D], ENRIN 1D [ENRI1D], TSH 1D [TSH1D] suspended due to BMT DVOR/DME shutdown period until 0000 UTC 10 JUL 2025.

VVCI, Catbi

Haiphong, From 1700Z 09 JUL 2025 to 1659Z 07 DEC 2025 aircraft stands number 1, 2, 3 will be temporarily suspended. Eff 09 Jul 25.

From 1700Z 28 FEB 2025 to 1659Z 10 FEB 2026 aircraft stands from 15 to 20 will be temporarily closed.

VVDL, Lien Khuong

Lam Dong, SID procs BMT 1F [BMT1F], BMT 1E [BMT1E] suspended due to BMT DVOR/DME shutdown period until 0000 UTC 10 JUL 2025.

STAR procs BMT 1G [BMT1G], BMT 1H [BMT1H] suspended due to BMT DVOR/DME shutdown period until 0000 UTC 10 JUL 2025.

VVNB, Noi Bai Intl

Hanoi, ILS U/T/S Rwy 11R, ILS T/S Rwy 29L, ILS U/T/S Rwy 29R, RNP X/W Rwy 11L and RNP X/W Rwy 11R apch procs temporary applied during construction period from 0100 to 1000 daily until 15 AUG 2025.

Phase 3: From 0200Z 01 JUN 2025 to 0159Z 01 JUL 2025 stands 7A, 30A, 12B, 28, 28A, 31A, 32A, 33A will be temporarily closed.

RNP Z/Y Rwy 11L, RNP Z/Y Rwy 11R, ILS Y/X/W Rwy 11R, ILS Y/X/W Rwy 29R, ILS Y/X Rwy 29L apch procs should not be used during construction period from 0100 to 1000 daily until 15 AUG 2025.

Trial Operation : From 0200Z 01 JUL 2025 to 0159Z 31 DEC 2025 stands 7A, 30A, 12B will be temporarily closed. Eff 01 Jul 25.

VVPK, Pleiku

Pleiku, SID procs MEVON 1R [MEVO1R], ENGIM 1R [ENGI1R], MEVON 1S [MEVO1S], ENGIM 1S [ENGI1S] suspended due to BMT DVOR/DME shutdown period until 0000 UTC 10 JUL 2025.

STAR procs MEVON 1T [MEVO1T], ENGIM 1T [ENGI1T], MEVON 1U [MEVO1U], ENGIM 1U [ENGI1U], suspended due to BMT DVOR/DME shutdown period until 0000 UTC 10 JUL 2025.

VVPQ, Duongdong

Phuquoc, Temporarily suspending the sequenced flashing light system at the beginning of Rwy 28 and Rwy 10.

VVTS, Tansonnhat

Hochiminh, Phase 3: From 0701Z 19 MAY 2025 to 0700Z 28 JUN 2025 stands 16, 16A, 16B will be temporarily closed due to construction.

PACIFIC

INTENTIONALLY LEFT BLANK